

REPLACEMENT FOR
X-TYPE '01

REPLACEMENT FOR
XJR/X300

REPLACEMENT FOR
X308

883-1401-AE X TYPE
SIDE LAMP
R 02C2S3046
L 02C2S3045
PCS CFT



W5W TBA

883-1404
SIDE LAMP
R LNA4812AB
L PCS CFT



W5W TBA

883-1602
FRONT LAMP
R LNC4800AD
L LNC4801AD
PCS CFT



P21W TBA

883-1401P3BE-C X TYPE
SIDE LAMP
50PRS 0.92CFT



WY5W

883-1403
FRONT REFLECTOR
DBC10889
PCS CFT



TBA

883-1402
SIDE LAMP
R LNC5020AB
L LNC5021AB
PCS CFT



TBA

883-1401P3BE-S X TYPE
SIDE LAMP
50PRS 0.92CFT



WY5W

883-1601
FRONT LAMP
R LNA4800AB
L LNA4801AB
PCS CFT



P21W TBA

883-1901 S TYPE
TAIL LAMP
R 2VP238021-02
L 2VP238021-01
PCS CFT



P21W/PY21W/P21/4W/R5W TBA

883-1903
TAIL LAMP
R L PCS CFT



PY21W/P21/5W/P21W/P21W/R5W TBA

883-1902
TAIL LAMP
R 2VP236009-02
L 2VP236009-01
PCS CFT



PY21W/P21/5W/P21W/P21W/R5W TBA