



REPLACEMENT FOR

SCANIA 112 '80- '88
SCANIA 113 '88- '96



REPLACEMENT FOR

SCANIA 114 '96-'04

REPLACEMENT FOR

SCANIA '05-'06

SCANIA

771-1103-LD-E 43T
HEAD LAMP
R 47-771-1103N
L 10PCS 1.88CFT
4PCS 6.78CFT

H4

771-1104-LD-E
HEAD LAMP
R 1EG007150101
L 1EG007150091
4PCS 5.00CFT

H4

771-1105-LD-EH
HEAD LAMP
R 1760554
L 1760551
PCS CFT

D2R/H7/T4W TBA

771-1501
CORNER LAMP
R
L
20PCS 3.10CFT
00-771-1501 LENS
50PCS 3.6CFT

771-1502-UE
CORNER LAMP
R 1337250
L 1385410
20PCS 3.40CFT

R5W/R5W/P21W

771-1503N-AE
CORNER LAMP
1747981
20PCS
3.8CFT

P21W TBA

771-1901-WE
TAIL LAMP
R
L
10PCS 2.50CFT
00-771-1901 LENS
20PCS 3CFT

771-2001
FOG LAMP
R
L
PCS CFT

TBA

771-2003-UE INNER
HIGH BEAM LAMP
R 1446354
L 1446353
12PCS
2.41CFT

H1

551-1949-AE
TAIL LAMP
R 5001847583
L 5001847582
6PCS 6.7CFT

R5W/P21W/P21W/P21W/R5W/R5W/P21W/P21W

771-2002-UE
FOG LAMP
R 1529071
L 1529070
L 1422991
6PCS 2.1CFT

H1/H1

771-2004-UE OUTER
FOG LAMP
R 1446356
L 1446355
12PCS
2.73CFT

H1

771-1902-AE
TAIL LAMP
R 1498103
L 1498102
R 1792374
L 1792375
PCS CFT

P21W/P21W/P21W/P21W/R5W/R5W/R5W TBA

771-1902-AE
TAIL LAMP
R 1498103
L 1498102
R 1792374
L 1792375
PCS CFT

P21W/P21W/P21W/P21W/R5W/R5W/R5W TBA

Toutes les pièces énumérées dans ce catalogue ne sont pas originaux. Alle die in diesem Katalog abgebildeten Artikel, sind nicht original Teile. All items shown in this catalogue are not original parts. Todos los productos de este catalogo no son originales. Tutti i particolari raffigurati in questo catalogo non sono originali.

SCANIA